OKLAHOMA DEPARTME	NT OF TRANSF	PORTA	ATION	7 - B 1	ridge I	Inspection	Report	
NBI No.: 14155 Structure No.: 3625			111011		Rating: 71 FO	_	Health Index:	
IDENTIFICATION	2003 A Local I				INSPECT	TION	71.0	
Description: IDENTIFICATION 30'-55'-55'-30' CONT.CONC SLAB SPANS W/ 2 -1.5' SAI 1. State:Oklahoma 2. SHD District: I 3. County Code: KAY 4. Place Code: Unk Admin. Area: Unknown	Division 4	Type NBI: FC Freq.: UW Freq.	Insp Req. N N	Insp Done Y N N	Freq: 24 NA NA	Insp. Date: 11/8/2017 NA NA	Next Insp.: 11/8/2019 NA NA	
5. Inventory Route (Route On Structure): 1 - 4 - 1 - E	0030 - 0	OS Freq.:		N	NA	NA	NA	
6. Feature Intersected: I-35 UNDER 7. Facility Carried: CO. RD. E0030 CO. RD. I 9. Location: 2 MI S KAN S/L 11. I 13. LRS Inv. Route./ Subroute.: -1 -1 16. Latitude: 36 58 12.99 17. I 98. Border Br. Code: Vot Applicab % Resp.: 0 99. B STRUCTURE TYPE AND MATE	CLASSIFICATION 12. Base Hwy Network: Not on Base Network 21. Custodian: 01State Highway Agency 26. Functional Class: 07 Rural Mjr Collecto 100. Defense Highway: 0 Not a STRAHNET h 101. Parallel Structure: No bridge exists 102. Dir. of Traffic: 2 2-way traffic 104. Highway System: 0 Not on NHS 105. Fed. Land Hwy 0 N/A (NBI) 110. National Truck Network: 0 Not part of na 112. NBIS Length: Long Enough							
Concrete Continuous Slab								
44. Approach Span Material and Design Type Not Applicable (P) Not App	58. Deck: 6 Satisfactory 59. Super.: 7 Good 60. Sub.: 6 Satisfactory 62. Culvert: N N/A (NBI) 61. Channel/Channel Protection: N N/A (NBI) Flowline Notes:							
AGE AND SERVICE		-		LOAD	RATING A	ND POSTING		
27. Year Built: 1958 106. Year Re 28A. Lanes on: 2 28B. Lanes Under: 4 29. ADT: 50 30. Year of ADT: 2015 42A. Type of Service on: 1 Highway 42B. Type of Service under: 1 Highway	31. Design Load: 2 M 13.5 (H 15) 41. Posting status: A Open, no restriction 63. Op. Rating Method: 1 LF Load Factor-Ton 64. Operating Rating (H / HS / 3-3): 27.4 40.3 68.8 66. Inventory Rating (H / HS / 3-3): 14.9 18.6 -1.1 65. Inv. Rating Method: 1 LF Load Factor-Tor 65. Inv. Rating Method: 1 LF Load Factor-Tor 66. Inventory Rating (H / HS / 3-3): 67. Inv. Rating Method: 1 LF Load Factor-Tor 68. Inv. Rating Method: 1 LF Load Factor-Tor 69. Inv. Rating Method: 1 LF Load Factor-Tor							
GEOMETRIC DATA		70. Posting: 5 At/Above Legal Loads Date Rated: 12/11/2007						
10. Inv. Rte. Min. Vert. Clr.: 328.1 ft 32. Approach Roadway Width (W/ Shoulders): 20.0 ft Deck Area: 4,294.8 sq. ft 33. Median: 34. Skew: 0 35. Structure I	PROPOSED IMPROVEMENTS 94. Bridge Cost: \$688,846 75. Type of Work: 31 Repl-Load Capacity 95. Roadway Cost: \$1,136,596 76. Lgth. of Improvment: 275.6 ft 96. Total Cost: \$1,928,769 114. Future ADT: 80 97. Year of Cost Est.: 2015 115. Year of Future ADT: 2035							
47. Inv. Rte. Total Horiz. Clr.: 20.0 ft 48. Length Maximum Span: 55.1 ft 49. Structure Length: 171.9 ft 50A. Curb/Sdwlk Wdth L: 1.5 ft 50B. Curb/Sidewalk Width R: 1.5 ft 51. Width Curb to Curb: 20.0 ft 52. Width Out to Out: 25.0 ft			NAVIGATION DATA 38. Navigation Control: NA-no waterway 39. Vertical Clearance: 0.0 ft 111. Pier Protection: Not Applicable (P) 116. Lift Bridge Vert. Clear.: 0.0 ft					
53. Minimum Vertical Clearance Over Bridge: 328.1 ft 54A/54B. Min. Vert. Underclearance: H Hwy beneath stru N/E Meas. N1600 N1602 -1 S1600 Post. DO NOT UDO NO	APPRAISAL 36A. Bridge Rail: 0 Substandard 36C. Approach Rail: 0 Substandard 36D. Approach Rail Ends: 0 Substandard 67. Str. Evaluation: 5 Above Min Tolerable 68. Deck Geometry: 5 Above Tolerable 69. Underclearance, Vertical and Horizontal: 2 Intolerable - Replace 71. Waterway Adequacy: N Not applicable 72. Approach Alignment: 8 Equal Desirable Crit 113. Scour Critical: N Not Over Waterway							
200c. Temperature: 45	214a. Posted Weight Limit:	NR			243. Gi	irder Spacing/Number	-1.0 / -1	
200d. Weather: CLEAR 201. Structural Steel ASTM Desig.: -1 202. Waterproof Membrane :-1 Date Installed: 1/1/1901 203. Type Exp. Dev.: _	b. Posted Speed Limit : c. Narrow/One Lane Bridge d. Vertical Clearance Sign: Advanced Warning Sign :	YES			30 55 55 245. Gi	pan Lengths: 30 -1 -1 irder Depth: -1.000	-1 -1	
204. Type of Handrail: BC 205. Material and Quantity: -1.0 208. Type of Abutment: Skeleton	e. Navigation Lights: Working/Not Working: 215. Overpass: A - Interstate	- -			246. O 246. O	verlay Depth Changed		
Type of Foundation : Concrete Piling 209. Type of Pier / Found.: 1 Pier Concrete Piling	221. Substructure Cond. (U/W) 222. Fill over RCB: 223. Appr. Slab/Rdwy Cond.:	: - -1 Good	l		2: _ 4: _	rotective Systems : 1: 3: 5:	- -	
210. Foundation Elev1.0 -1.0 -1.0 -1.0 -1.0 -1.0 -1.0 -1.	225. Paint Type : Overcoat : 226. Date Painted:		Applicable Applicable		249. Sc	o. of Field Splices w/ cour Crit. POA exists? ulvert Headwall Dist.:	: _	
Date Installed: 1/1/1901 213. Utilities Attached: -1 -1 -1 -1	227. Paint Coloring: 233. Deck Forming: Convention 238. School Bus Rte: Current a	-1 onal Formin			257a. C 258. Pl	han. Profile Up/Down OkiePROS Auto. Truck ans w/ found. are in fictour Eval. is in file at 0	k Routing No le at ODOT:	

1/4/2018 Page 1 of 2

259. Scour Eval. is in file at ODOT:
263. Interchange at Intersection: No Interchange
264. Interstate Milepoint: 233.78

238. School Bus Rte: Current and Desired Route 240. Appr. Roadway Type: Gravel

-1

-1

-1

OKLAHOMA DEPARTMENT OF TRANSPORTATION -

Bridge Inspection Report Suff. Rating: 71.1

Health Index:

NBI No.: 14155 Structure No.: 3625 2605 X Local ID:-1 FO 71.8 11/8/2017 Reported By: **GHINES** Inspection Date:

Inspected With: Gary Richardson Invoice No.: -1 Agency:

Structure / Inspection Notes

Maximum horizontal clearance below: N.B.= 43', S.B.=49.4' due to cable barriers & crash barrels.

G Hines inspection comments - 11/8/2017

PX - All approach rails (above) needs updated to meet standards * PX - All OM-3's are down (above) * Safety below = 1111 * Satisfactory to good gravel approach roadway * 36' wide roadway below each direction * The slopewalls are in satisfactory to good condition - minor settlement is causing a small cavity to develop at the top on the NW & NE areas * Satisfactory

Elm.	Env.	Description	Un.	Qty.	Qty.St. 1	% 1	Qty.St. 2	% 2	Qty.St. 3	% 3	Qty.St. 4	% 4	Qty.St. 5	% 5
38	4	Reinforced Concrete Slab	(SF)	3,438	0	0 %	3,438	100 %	0	0 %	0	0 %	0	0 %
205	4	Reinforced Conc Column or Pile Extension	(EA)	4	1	17 %	1	33 %	2	50 %	0	0 %	0	0 %
215	4	Reinforced Conc Abutment	(LF)	49	33	67 %	12	24 %	4	8 %	0	0 %	0	0 %
234	4	Reinforced Conc Cap	(LF)	69	64	93 %	2	3 %	3	4 %	0	0 %	0	0 %
310	4	Elastomeric Bearing	(EA)	5	5	100 %	0	0 %	0	0 %	0	0 %	0	0 %
331	4	Reinforced Conc Bridge Railing	(LF)	344	314	91 %	22	6 %	8	2 %	0	0 %	0	0 %
859	4	Soffit of Concrete Decks and Slabs	(EA)	1	0	0 %	1	100 %	0	0 %	0	0 %	0	0 %
958	4	Concrete Cracking	(EA)	1	0	0 %	0	0 %	0	0 %	1	100 %	0	0 %
967	4	Substructure Trafic Impact	(EA)	1	1	100 %	0	0 %	0	0 %	0	0 %	0	0 %

Additional

Elements

Elem.	Element Notes (Include Size and Location of Deterioration								
	FX - Light wear & popouts in the wheel lanes. Some minor scrapes from grader noted. The deck is covered with light to moderate pattern cracking. A few small spalls developing no exposed rebar. Soil needs cleaned of the curbs - grader needs to refrain from grading across the deck.								
205	Moderate scaling on the North face of the 1st column near the bottom with defects at old rail mounting holes. Small spalls present on the 2nd column at the SE corner (mainly from insufficient cover). Spall at SE corner of 3rd column is due to impact (see 967). Rebar is exposed on SW area of bent #3. Satisfactory condition overall.								
215	Superficial weathering overall - some minor water stains. Rebar is visible at the lower NW are due to insufficient cover. A small delamination is present at the upper NW area. There are 10 to 12 small popout-type spalls (snap ties) noted. Some light pattern cracking noted at the SE area.								
234	One tiny spall on the NW area & the lower north area of the bent #1 cap. Some spalling is present on the lower SE area of bent #2. Also a tiny spall noted at the SW end of the bent #3 cap with scaling & popouts at the ends,. Superficial weathering otherwise.								
310	< none >								
331	1 Three rail sections on the North in span #3 have been patched in the past. The patches are cracking & crumbling out at the posts (2009 photo). Some other tiny spalls noted on a few other posts - the NE & SE corner posts are chipped. Not serious at this time. Minor weathering overall.								
859	Minor pattern cracking & light staining on the fascia areas - some efflorescence noted on the north fascia near bent #2. There is an embedded wire at the NW area of span #3 that is spalling out.								
958	PX - Light to moderate transverse & pattern cracking in all areas. Most cracks in spans #2 & 3 are less than .25 foot apart. Needs a thin overlay to seal & protect the deck.								
967	967 FX - The SE corner of the 3rd column has a small impact spall - not serious at this time. There are tiny chips scrapes in the south area of the 3rd cap.								
Roadway Name: I-35 UNDER NBI Information Applicable To The Route Under The Structure									
5. In	ventory Route (Route Under Structure: 2 - 1 - 1 - 00035 - 0								
10. M	in. Vert. Clr.(ft.): 15.8 28b. Lanes Und.: 4 104. Highway System: 1 On the NHS								

Roadway Name: I-35 UNDER NBI Information Applicable To The Route Under The Structure								
5. Inventory Route (Route I	Under Structure: 2 - 1	- 1 - 00035 - 0		102. Traffic Dir.:	2 2-way traffic			
10. Min. Vert. Clr.(ft.):	15.8	28b. Lanes Und.:	4	104. Highway System:	1 On the NHS			
12. Base Hwy Network:	On Base Network	29. ADT:	14400	105. Fed Land Hwy:	0 N/A (NBI)			
13. LRS Inv. Rt./ Subroute:	3625 W0000 / 06	32. Appr. Roadway Width (ft.):	74.0	109. Truck ADT%:	36			
19. Detour Len.(Mi.):	0.0	47. Total Horiz. Clr.(ft.):	49.4	110. Natl. Truck Network:	1 Part of natl network			
20. Toll Facility:	3 On free road	51. Roadway Width (ft.):	74.0	114. Future ADT:	23040			
26. Function Class.: 01 Rural Interstate 100. Defense Highway: 1 On Interstate STRAHNET								
Agency Field: 1.(Under Rte.): U 2.(Vert. X-Ref.): -1 3.(Compass Dir.): N 4.(Vert. Post. Inc.): 1507 5.(Vert. Post. Dec.): 1508								

1/4/2018 Page 2 of 2