OKLAHOMA DEPARTMEN	NT OF TRANSP	PORTATI		Brid Suff. Ratio		tion Report Health Index:
NBI No.: 14408 Structure No.: 3625 0	698WX Local I	ID:-1	,	NE	• •	66.6
Description: <u>IDENTIFICATION</u>				<u>IN</u>	NSPECTION .	
30'-45'-45'-30' CONT. CONC SLAB SPANS		Type Inst	Req. Insp	Done F	req: Insp. 1	Date: Next Insp.:
1. State: Oklahoma 2. SHD District: Di		NBI:		Y	24 11/2/2	
3. County Code: KAY 4. Place Code: TON	KAWA	1 1			NA NA	
Admin. Area: Unknown 5. Inventory Route (Route On Structure): 1 - 1 - 1 - 000	035 - 0				NA NA NA NA	
6. Feature Intersected: U.S. 60 UNDER	0	OS Freq				11/4
7. Facility Carried: I-35		12. Base Hwy N	etwork : On I		SSIFICATION 20 Toll Facility	y: 3 On free road
	file Post: 6.979 mi	21. Custodian: 0			•	State Highway Agency
13. LRS Inv. Route./ Subroute.: 3625 W0000 01 16. Latitude: 36 41 42.48 17. Lo	ongitude: 097 20 45.65	26. Functional 0	Class: 01 Rura	al Interstate	37. Historical S	Sig.: 5 Not eligible for NRHP
	rder Br. #: Unknown					ructure: Left of bridge
STRUCTURE TYPE AND MATE	RIALS	102. Dir. of Traf 104. Highway S	-			acture: Not Applicable (P) I Hwy 0 N/A (NBI)
43. Main Span Material and Design Type			-		ne 112. NBIS Len	- · · · · · · · · · · · · · · · · · · ·
Concrete Continuous Slab 44. Approach Span Material and Design Type		-				
Not Applicable (P) Not Applicabl		58. Deck: 6 Sa	tiefactory		ONDITION er.: 5 Fair	60. Sub.: 5 Fair
45. No. of Spans Main Unit: 4 46. No. of Approach	h Spans: 0	62. Culvert: N	-		nnel/Channel Protec	
107. Deck Type: 1 Concrete-Cast-in-Place108A. Wearing Surface: 6 Bituminous		Flowline Notes		or. Chai	mer channer i rotee	tion. TVTV/T(TVBI)
108B. Membrane: 8 Unknown						
108C. Deck Protection: 8 Unknown						
AGE AND SERVICE				LOAD RAT	TING AND POSTIN	
27. Year Built: 1959 106. Year Rec	onstructed: -4	31. Design Loa	d: 5 MS 18 (I			tus: A Open, no restriction
28A. Lanes on: 2 28B. Lanes Under: 4	19. Detour Length: 0.1 mi	63. Op. Rating	Method: 1 LF	Load Factor-	Ton Alt. Op. Rating	Meth.: 1 LF Load Factor-To
29. ADT: 8750 30. Year of ADT: 2015	109. Truck ADT %: 36	64. Operating I	Rating (H / HS	3/3-3):	26.7	42.4 68.2
42A. Type of Service on: 1 Highway 42B. Type of Service under: 1 Highway		66. Inventory R			16.0	25.5 40.9
42B. Type of Service under. 1 Trighway		_				g Meth.: 1 LF Load Factor-Toi
GEOMETRIC DATA		70. Posting: 5 A	At/Above Leg		Date Rated :	
10. Inv. Rte. Min. Vert. Clr.: 328.1 ft		94. Bridge Co	st: \$688,84		D IMPROVEMENT	Work: 31 Repl-Load Capacit
32. Approach Roadway Width (W/ Shoulders): 38.0 ft		94. Bridge Co				Improvment: 275.6 ft
Deck Area: 6,533.7 sq. ft 33. Median: (96. Total Cost	\$1,928,	769	114. Future A	DT: 14000
34. Skew: 0 35. Structure Fl 47. Inv. Rte. Total Horiz. Clr.: 38.0 ft	ared: 0 No flare	97. Year of Co	ost Est.: 201	5	115. Year of I	Future ADT: 2035
48. Length Maximum Span:44.9 ft 49. Structure	Length: 151.9 ft				IGATION DATA	
50A. Curb/Sdwlk Wdth L: 0.2 ft 50B. Curb/Side		 Navigation Vertical C 				al Clearance: 0.0 ft
51. Width Curb to Curb: 38.0 ft 52. Width Ou	t to Out: 43.0 ft	111. Pier Prote				ge Vert. Clear.: 0.0 ft
53. Minimum Vertical Clearance Over Bridge: 328.1 ft 54A/54B. Min. Vert. Underclearance: H Hwy beneath struct	15.6 ft			<u> </u>	APPRAISAL	
N/E S/W	15.010	36A. Bridge R	ail: 1 Meets S	tandards	36C. Approach I	Rail: 1 Meets Standards
Meas. E1510 E1601 -1 W1510	W1601 -1	36B. Transitio				Rail Ends: 1 Meets Standards
	T U DIV. 4 -1				ntal: 4 Tolerable	metry: 6 Equal Min Criteria
55A/55B. Minimum Lateral Undrclearance R: H Hwy beneal	th struct 9.6 ft	71. Waterway				
56. Minimum Lateral Undrclearance L: 6.7 ft		72. Approach				
		113. Scour Cri	tical: N Not	Over Waterwa	ч	
200c. Temperature: 74	214a. Posted Weight Limit:	NR		1	243. Girder Spacing	
200d. Weather: CLEAR 201. Structural Steel ASTM Desig.: -1 -1	b. Posted Speed Limit :c. Narrow/One Lane Bridge	70 sign: NO			244. Span Lengths 30	: 30 -1
202. Waterproof Membrane :-1	d. Vertical Clearance Sign:	YES				-1 -1
Date Installed: 1/1/1901	Advanced Warning Sign :	NO				-1
203. Type Exp. Dev. : _					245. Girder Depth : 246. Type of Overla	
-	e. Navigation Lights :				246. Overlay Thick	•
204. Type of Handrail: Parapet Retrofit 205. Material and Quantity: -1.0	Working/Not Working :	_			246. Overlay Date:	
208. Type of Abutment : Skeleton	215. Overpass: A - Interstate					Changed > 1"? No
Type of Foundation : Concrete Piling	221. Substructure Cond. (U/W)				247. Protective Sys	stems : 1: _ 3: _
209. Type of Pier / Found.: 3 Piers Yes	222. Fill over RCB:	-1 Satisfactor	v		2 4: _	5: _
Concrete Piling	223. Appr. Slab/Rdwy Cond.:	Saustacion	,		248. No. of Field S	plices w/ Corrosion : -1
210. Foundation Elev1.0 -1.0 9475.0 9465.0 -1.0	225. Paint Type:	Not Applic			249. Scour Crit. PC	
	Overcoat :	Not Applic	able		250. Culvert Heady	vall Dist.: -1.0
211. Wear. Surf. Prot. System : None Date Installed : 1/1/1901	226. Date Painted:227. Paint Coloring:	-1 -1			256. Chan. Profile	Up/Down Stream?:
213. Utilities Attached : -1	233. Deck Forming: Convention				257a. OkiePROS A	uto. Truck Routing Yes
-1 -1 -1	238. School Bus Rte: Current a	nd Daginal Bases			258. Plans w/ found 259. Scour Eval. is	d. are in file at ODOT:
-1 -1 -1	240. Appr. Roadway Type: Asp			I		Intersection: Full Interchang
					264. Interstate Mile	-
			_		_	

Page 1 of 2 1/4/2018

OKLAHOMA DEPARTMENT OF TRANSPORTATION -

Bridge Inspection Report

NBI No.: **14408** Structure No.: 3625 0698WX Local ID:-1 Suff. Rating: 75.7 Health Index: 66.6

Inspection Date:	11/2/2017	Reported By:	GHINES
Invoice No.:	-1	Inspected With:	Gary Richardson
		Agency:	

Structure / Inspection Notes

THE 'EX' BRIDGE CONTROLS THE UNDER CLEARANCES FOR THIS PAIR OF BRIDGES. THIS BRIDGE IS IN THE TONKAWA CITY LIMITS.

G Hines inspection comments - 11/02/2017

FX - Safety below = 0000; the bents should have protection added soon * FX - The erosion present at the SW wing & slopewall area has had some repairs * The roadway below is 38' wide in each direction * Total clearance below: E.B.=42.5' * All OM-3's are in place below * The retro-fit rail has eliminated most of the curb width *

Elm.	Env.	Description	Un.	Qty.	Qty.St. 1	% 1	Qty.St. 2	% 2	Qty.St. 3	% 3	Qty.St. 4	% 4	Qty.St. 5	% 5
38	4	Reinforced Concrete Slab	(SF)	5,772	0	0 %	4,272	74 %	1,500	26 %	0	0 %	0	0 %
205	4	Reinforced Conc Column or Pile Extension	(EA)	9	1	11 %	8	89 %	0	0 %	0	0 %	0	0 %
215	4	Reinforced Conc Abutment	(LF)	90	0	0 %	90	100 %	0	0 %	0	0 %	0	0 %
234	4	Reinforced Conc Cap	(LF)	123	90	73 %	27	22 %	6	5 %	0	0 %	0	0 %
310	4	Elastomeric Bearing	(EA)	5	5	100 %	0	0 %	0	0 %	0	0 %	0	0 %
331	4	Reinforced Conc Bridge Railing	(LF)	305	303	99 %	2	1 %	0	0 %	0	0 %	0	0 %
510	4	Wearing Surfaces	(SF)	5,772	4,272	74 %	1,500	26 %	0	0 %	0	0 %	0	0 %
859	4	Soffit of Concrete Decks and Slabs	(EA)	1	0	0 %	0	0 %	1	100 %	0	0 %	0	0 %
924	4	Concrete Railing Protective Coating	(SF)	1,753	0	0 %	0	0 %	0	0 %	1,753	100 %	0	0 %
962	4	Superstructure Traffic Impact	(EA)	1	0	0 %	1	100 %	0	0 %	0	0 %	0	0 %

Additional

Elements

Elem.		Element Notes (Include Size	e and Location of Det	erioration	
38	The overlay was redone since the 2009 inspection.	Looks good in the wheel lanes. Down	n-graded due to soffit con	lition (see element #859).	_
205	Minor scaling at the bottom of most columns. Ligh	t cracks on the lower 1 ft on the 1st &	2nd piers in bents #1 & 3	and on the 2nd pier in bent	#2. Satisfactory condition overall.
215	Cleaned & repaired by State Forces on 11-1-2017 ((photo @ North).			
234	One minor spall on the NW end of the 1st cap & at scaling & small popouts on the ends of the 1st & 3.		t on the West face & a sm	all delamination is present or	n the 2nd cap at the NW end. Lots o
310	< none >				
331	FX - The parapet retro-fit rails are in good condition	on overall. Some superficial cracks no	ted.		
510	FX - The overlay was redone since the 2009 inspec	ction. Good condition in the wheel lan	es. The West shoulder ha	s minor rutting, raveling, & c	cracking present.
	FX - Light to moderate pattern cracking, minor dis 35% of span #4 has some type of distress. Rebar is cleaned off since 2007. Spalls noted at most joints	visible along the lower west edge of			
	35% of span #4 has some type of distress. Rebar is	visible along the lower west edge of with some active leaching present.			
924	35% of span #4 has some type of distress. Rebar is cleaned off since 2007. Spalls noted at most joints	visible along the lower west edge of with some active leaching present. on the West faces.	span #1. Very heavy efflo		
924 962	35% of span #4 has some type of distress. Rebar is cleaned off since 2007. Spalls noted at most joints FX - The waterproof protective coating has failed of there are 3 minor chipped areas at the lower west.	visible along the lower west edge of with some active leaching present. on the West faces. edge of span #2 & one on the east low	span #1. Very heavy efflover edge of span #3.	rescence on the West fascia a	
924 962 Road	35% of span #4 has some type of distress. Rebar is cleaned off since 2007. Spalls noted at most joints FX - The waterproof protective coating has failed of there are 3 minor chipped areas at the lower west way Name: U.S. 60 UNDER	visible along the lower west edge of with some active leaching present. on the West faces. edge of span #2 & one on the east low NBI Information Applicable To The	span #1. Very heavy efflover edge of span #3.	rescence on the West fascia a	area in span #1. The loose areas wer
924 962 Road	35% of span #4 has some type of distress. Rebar is cleaned off since 2007. Spalls noted at most joints FX - The waterproof protective coating has failed of there are 3 minor chipped areas at the lower west way Name: U.S. 60 UNDER ventory Route (Route Under Structure: 2 - 2	visible along the lower west edge of swith some active leaching present. on the West faces. edge of span #2 & one on the east low NBI Information Applicable To Ti - 1 - 00060 - 0	span #1. Very heavy efflover edge of span #3.	rescence on the West fascia a leture 102. Traffic Dir.:	area in span #1. The loose areas wer
924 962 Roady 5. Inv	35% of span #4 has some type of distress. Rebar is cleaned off since 2007. Spalls noted at most joints FX - The waterproof protective coating has failed of there are 3 minor chipped areas at the lower west way Name: U.S. 60 UNDER ventory Route (Route Under Structure: 2 - 2 in. Vert. Clr.(ft.): 15.6	visible along the lower west edge of swith some active leaching present. on the West faces. edge of span #2 & one on the east low NBI Information Applicable To To 1 - 00060 - 0 28b. Lanes Und.:	span #1. Very heavy efflover edge of span #3.	icture 102. Traffic Dir.: 104. Highway System :	2 2-way traffic 0 Not on NHS
924 962 Roady 5. Inv 10. M	35% of span #4 has some type of distress. Rebar is cleaned off since 2007. Spalls noted at most joints FX - The waterproof protective coating has failed of there are 3 minor chipped areas at the lower west way Name: U.S. 60 UNDER ventory Route (Route Under Structure: 2 - 2 in. Vert. Clr.(ft.): 15.6 ase Hwy Network: On Base Network	visible along the lower west edge of swith some active leaching present. on the West faces. edge of span #2 & one on the east low NBI Information Applicable To To - 1 - 00060 - 0 28b. Lanes Und.: 29. ADT:	yer edge of span #3. he Route Under The Strate 4 1500	icture 102. Traffic Dir.: 104. Highway System: 105. Fed Land Hwy:	2 2-way traffic 0 Not on NHS 0 N/A (NBI)
924 962 Roady 5. Inv 10. M	35% of span #4 has some type of distress. Rebar is cleaned off since 2007. Spalls noted at most joints FX - The waterproof protective coating has failed of there are 3 minor chipped areas at the lower west way Name: U.S. 60 UNDER ventory Route (Route Under Structure: 2 - 2 in. Vert. Clr.(ft.): 15.6	visible along the lower west edge of swith some active leaching present. on the West faces. edge of span #2 & one on the east low NBI Information Applicable To To 1 - 00060 - 0 28b. Lanes Und.: 29. ADT: 32. Appr. Roadway Width (ft.):	rer edge of span #3. he Route Under The Str	icture 102. Traffic Dir.: 104. Highway System :	area in span #1. The loose areas we 2 2-way traffic 0 Not on NHS
924 962 Roady 5. Inv 10. M 12. Ba 13. Ll 19. Do	35% of span #4 has some type of distress. Rebar is cleaned off since 2007. Spalls noted at most joints FX - The waterproof protective coating has failed of there are 3 minor chipped areas at the lower west way Name: U.S. 60 UNDER ventory Route (Route Under Structure: 2 - 2 in. Vert. Clr.(ft.): 15.6 ase Hwy Network: On Base Network RS Inv. Rt./ Subroute: 3602 0000 / 01 etour Len.(Mi.): 0.0	visible along the lower west edge of swith some active leaching present. on the West faces. edge of span #2 & one on the east low NBI Information Applicable To To 1 - 00060 - 0 28b. Lanes Und.: 29. ADT: 32. Appr. Roadway Width (ft.): 47. Total Horiz. Clr.(ft.):	yer edge of span #3. he Route Under The Strategy 4 1500 76.0 42.4	Icture 102. Traffic Dir.: 104. Highway System: 105. Fed Land Hwy: 109. Truck ADT%: 110. Natl. Truck Network:	2 2-way traffic 0 Not on NHS 0 N/A (NBI) 16 0 Not part of natl netwo
924 962 Roady 5. Inv 10. M 12. Ba 13. Ll 19. Do 20. To	35% of span #4 has some type of distress. Rebar is cleaned off since 2007. Spalls noted at most joints FX - The waterproof protective coating has failed of there are 3 minor chipped areas at the lower west way Name: U.S. 60 UNDER ventory Route (Route Under Structure: 2 - 2 in. Vert. Clr.(ft.): 15.6 ase Hwy Network: On Base Network RS Inv. Rt./ Subroute: 3602 0000 / 01	visible along the lower west edge of swith some active leaching present. on the West faces. edge of span #2 & one on the east low NBI Information Applicable To To 1 - 00060 - 0 28b. Lanes Und.: 29. ADT: 32. Appr. Roadway Width (ft.):	yer edge of span #3. he Route Under The Strate 4 1500 76.0	Icture 102. Traffic Dir.: 104. Highway System: 105. Fed Land Hwy: 109. Truck ADT%:	2 2-way traffic 0 Not on NHS 0 N/A (NBI)

1/4/2018 Page 2 of 2