## Bridge Inspection Report Suff. Rating: 72.1 Health Index FO 85.4 OKLAHOMA DEPARTMENT OF TRANSPORTATION -Health Index: 85.4 NBI No.: **15145** Structure No.: 3625 1199 X Local ID:-1

NBI No.: <b>15145</b> Structure No.: 3625 1	199 X Local I	ID:-I			FO		85.4	
Description: <u>IDENTIFICATION</u>			ĺ					
30'-55'-55'-30' CONT. CONC SLAB SPANS W/ 2-1.5' SAF	ETY CURBS	<u>Type</u>	Insp Req.	Insp Done	Freq:	Insp. Date:	Next Insp.:	
State: Oklahoma     SHD District: Distric	ivision 4	NBI:		Y	24	11/13/2017	11/13/2019	
3. County Code: KAY 4. Place Code: Unkr		FC Freq.:	N	N	NA	NA	NA	
Admin. Area: Unknown	UW Freq.:	N	N	NA	NA	NA		
5. Inventory Route (Route On Structure): 1 - 4 - 1 - E0	OS Freq.:	N	N	NA	NA	NA		
6. Feature Intersected: I-35 UNDER				CLASSIE	ICATION			
7. Facility Carried: CO. RD. E0170 CO. RD. E		12 Base Hu	vv Network		CLASSIF Network	20. Toll Facility: 3 On fr	ee road	
	file Post: 11.987 mi	1		Highway Agend		22. Owner: 01 State High		
13. LRS Inv. Route./ Subroute.: -1 -1				07 Rural Mjr Co	•	37. Historical Sig.: 5 Not		
	ongitude: 097 20 46.43 order Br. #: Unknown	100. Defens	e Highway:	0 Not a STRAI		101. Parallel Structure: N	·	
		102. Dir. of	Traffic:2 2-	way traffic		103. Temp. Structure: No	t Applicable (P)	
STRUCTURE TYPE AND MATE	<u>ERIALS</u>	104. Highw	ay System:	0 Not on NHS		105. Fed. Land Hwy 0 N	/A (NBI)	
43. Main Span Material and Design Type Concrete Continuous Slab		110. Nation	al Truck Ne	twork: ) Not pa	art of na	112. NBIS Length: Long	Enough	
44. Approach Span Material and Design Type					COND	NITION		
Not Applicable (P) Not Applicable	CONDITION  58. Deck: 6 Satisfactory  59. Super.: 7 Good  60. Sub.: 6 Satisfactory							
45. No. of Spans Main Unit: 4 46. No. of Approac		t: N N/A (N			Channel Protection: N N	·		
107. Deck Type: 1 Concrete-Cast-in-Place	Flowline N		NBI) 01.	Chamiei/C	Channel Protection: IV IV	A (NDI)		
108A. Wearing Surface: 0 None		1 IOWING I						
108B. Membrane: 0 None 108C. Deck Protection: None								
AGE AND SERVICE				LOAD	RATING	AND POSTING		
	constructed: -4	31. Design	Load: 2 M	13.5 (H 15)		41. Posting status: A Op	en, no restriction	
28A. Lanes on: 2 28B. Lanes Under: 4	19. Detour Length: 2.0 mi	63. Op. Ra	ting Method	d: 1 LF Load Fa	actor-Ton	Alt. Op. Rating Meth.: 1	LF Load Factor-To	
29. ADT: 50 30. Year of ADT: 2015	109. Truck ADT %: 15	64. Operati	ng Rating (	H/HS/3-3):		30.0 41.0	69.2	
42A. Type of Service on: 1 Highway	66. Inventory Rating ( H / HS / 3-3 ): 14.9 18.6 -1.1							
42B. Type of Service under: 1 Highway		65. Inv. Ra	ting Method	d: 1 LF Load F	actor-Tor	Alt. Inv. Rating Meth.: 1	LF Load Factor-Toı	
		70. Posting	: 5 At/Abov	ve Legal Loads		Date Rated: 12/11/200	7	
GEOMETRIC DATA				PROF	POSED IM	IPROVEMENTS		
10. Inv. Rte. Min. Vert. Clr.: 328.1 ft			Cost: \$	6688,846		75. Type of Work: 31	Repl-Load Capacit	
32. Approach Roadway Width (W/ Shoulders): 21.4 ft	95. Roady	vay Cost: \$	31,136,596		76. Lgth. of Improvme			
Deck Area: 4,983.7 sq. ft 33. Median:	96. Total	Cost: \$	51,928,769		114. Future ADT: 80			
	lared: 0 No flare	97. Year o	f Cost Est.:	2015		115. Year of Future AD	T: 2035	
47. Inv. Rte. Total Horiz. Clr.: 24.0 ft 48. Length Maximum Span:55.1 ft 49. Structure	Length: 171.9 ft				NAVIGAT	ΓΙΟΝ DATA		
48. Length Maximum Span: 55.1 ft 49. Structure 50A. Curb/Sdwlk Wdth L: 1.5 ft 50B. Curb/Side	38. Navigation Control: NA-no waterway							
51. Width Curb to Curb: 24.0 ft 52. Width Ou	39. Vertical Clearance: 0.0 ft 111. Pier Protection: Not Applicable (P) 40. Horizontal Clearance: 0.0 ft 116. Lift Bridge Vert. Clear::0.0 ft							
53. Minimum Vertical Clearance Over Bridge: 328.1 ft	nt to Out: 29.0 ft	111. Pier I	rotection:	Not Applicable	: (P)	116. Lift Bridge Vert. C	lear.: 0.0 It	
54A/54B. Min. Vert. Underclearance: H Hwy beneath struc	t 16.0 ft				APPR	AISAL		
<u>N/E</u> <u>S/W</u>			ge Rail: 0 S			6C. Approach Rail:	0 Substandard	
Meas. N1601 N1602 -1 S1602	S1602 -1		sition: 0 S			6D. Approach Rail Ends:		
Post. DO NOT I DO NOT I DO NOT I						68. Deck Geometry: 6 E	Iqual Min Criteria	
				Vertical and Ho lacy: N Not ap		2 Intolerable - Replace		
55A/55B. Minimum Lateral Undrclearance R: H Hwy benea	th struct 9.5 ft			nent: 8 Equal D	-	"rit		
56. Minimum Lateral Undrclearance L: 18.6 ft				N Not Over Wa		31R		
	014 B . 1W**** ***	!	Jana Jana	5 . 61 / 140				
200c. Temperature: 51	214a. Posted Weight Limit: b. Posted Speed Limit:	NR NR				Girder Spacing/Number	: -1.0 / -1	
200d. Weather: CLOUDY 201. Structural Steel ASTM Desig.: -1 -1	c. Narrow/One Lane Bridge					Span Lengths:	-1	
202. Waterproof Membrane :-1	d. Vertical Clearance Sign:	YES				55 -1	-1	
Date Installed: 1/1/1901	Advanced Warning Sign :					55 -1		
203. Type Exp. Dev. : _	- 0					Girder Depth: -1.000		
-						Type of Overlay :		
204. Type of Handrail: BC	e. Navigation Lights :	-			1 ~	Overlay Thickness: 0		
205. Material and Quantity: -1.0	Working/Not Working:	-				•	/1901	
208. Type of Abutment : Skeleton	215. Overpass : A - Interstate					Overlay Depth Changed Protective Systems: 1:		
Type of Foundation : Concrete Piling	221. Substructure Cond. (U/W)				2:			
209. Type of Pier / Found.: 1 Pier _	222. Fill over RCB:	-1 Good			4:			
No Piling or Drilled Shaft	223. Appr. Slab/Rdwy Cond.:	Good				No. of Field Splices w/ 0		
210. Foundation Elev1.0 -1.0	225. Paint Type:	Not Ar	plicable			Scour Crit. POA exists?:		
-1.0 -1.0 -1.0	Overcoat:	-	plicable			Culvert Headwall Dist.:		
211. Wear. Surf. Prot. System : None	226. Date Painted:	-1	_				_	
Date Installed: 1/1/1901	227. Paint Coloring:	-1			256.	Chan. Profile Up/Down	Stream?:	

200c. Temperature: 51 200d. Weather: CLOUDY 201. Structural Steel ASTM Desig.: -1 202. Waterproof Membrane: -1 214a. Posted Weight Limit: b. Posted Speed Limit: c. Narrow/One Lane Bridge si d. Vertical Clearance Sign:	NR NR	243. Girder Spacing/Number: -1.0 / -1
Date Installed: 1/1/1901 Advanced Warning Sign:  203. Type Exp. Dev.: _	ign : NO YES NO	244. Span Lengths:  30 30 -1  55 -1 -1  245. Girder Depth: -1.000  246. Type of Overlay:
204. Type of Handrail: BC 205. Material and Quantity: -1.0 208. Type of Abutment: Skeleton Type of Foundation: Concrete Piling 209. Type of Pier / Found.: 1 Pier No Piling or Drilled Shaft  e. Navigation Lights: Working/Not Working: 215. Overpass: A - Interstate 221. Substructure Cond. (U/W): 222. Fill over RCB: 223. Appr. Slab/Rdwy Cond.:	- - - -1 Good	246. Overlay Thickness: 0 246. Overlay Date: 1/1/1901 246. Overlay Depth Changed > 1"? No 247. Protective Systems: 1: _ 2: _ 3: _ 4: _ 5: _
210. Foundation Elev1.0 -1.0 -1.0 -1.0 -1.0 -1.0 -1.0 -1.	Not Applicable Not Applicable -1 -1 nal Forming	248. No. of Field Splices w/ Corrosion: -1 249. Scour Crit. POA exists?: _ 250. Culvert Headwall Dist.: -1.0  256. Chan. Profile Up/Down Stream?: _ 257a. OkiePROS Auto. Truck Routing No 258. Plans w/ found. are in file at ODOT:
-1 -1 -1 238. School Bus Rte: Current and 240. Appr. Roadway Type: Grave		259. Scour Eval. is in file at ODOT: 263. Interchange at Intersection: No Interchange 264. Interstate Milepoint: 219.72

## **OKLAHOMA DEPARTMENT OF TRANSPORTATION -**

**Bridge Inspection Report** Suff. Rating: 72.1

Health Index:

Structure No.: 3625 1199 X FO NBI No.: 15145 Local ID:-1 85.4 11/13/2017 GHINES Inspection Date: Reported By:

Inspected With: Gary Richardson Invoice No.: -1 Agency:

## Structure / Inspection Notes

Maximum horizontal clearance below: N.B.= 45', S.B.=46.4' due to cable barriers & crash barrels.

G Hines inspection comments - 11/13/2017

PX - All of the slopewall joints are separated with vegetation growing in the cracks - the lower NW & NE areas are damaged \* PX - There is a large cavity under the SE abutment area \* Safety below = 1111 \* PX - Separation, settlement, & cavities at each side drain at the top - the SE one is destroyed with erosion into the roadway edge \* Good gravel roadway \* PX - All OM-3's are down or lean badly \*

Elm.	Env.	Description	Un.	Qty.	Qty.St. 1	% 1	Qty.St. 2	% 2	Qty.St. 3	% 3	Qty.St. 4	% 4	Qty.St. 5	% 5
38	4	Reinforced Concrete Slab	(SF)	4,126	2,888	70 %	1,238	30 %	0	0 %	0	0 %	0	0 %
205	4	Reinforced Conc Column or Pile Extension	(EA)	3	0	0 %	2	67 %	1	33 %	0	0 %	0	0 %
215	4	Reinforced Conc Abutment	(LF)	62	59	95 %	3	5 %	0	0 %	0	0 %	0	0 %
234	4	Reinforced Conc Cap	(LF)	81	65	80 %	7	9 %	9	11 %	0	0 %	0	0 %
310	4	Elastomeric Bearing	(EA)	5	5	100 %	0	0 %	0	0 %	0	0 %	0	0 %
331	4	Reinforced Conc Bridge Railing	(LF)	344	300	87 %	13	4 %	25	7 %	6	2 %	0	0 %
859	4	Soffit of Concrete Decks and Slabs	(EA)	1	0	0 %	1	100 %	0	0 %	0	0 %	0	0 %
958	4	Concrete Cracking	(EA)	1	0	0 %	1	100 %	0	0 %	0	0 %	0	0 %
962	4	Superstructure Traffic Impact	(EA)	1	0	0 %	1	100 %	0	0 %	0	0 %	0	0 %
967	4	Substructure Trafic Impact	(EA)	1	0	0 %	1	100 %	0	0 %	0	0 %	0	0 %

Additional

Elements

Elem.	Element Notes (Include Size and Location of Deterioration							
38	Some minor wear & grader scrapes - some older skim patches noted in spans #1 & #3. Minor scaling is present in two areas. Light to moderate longitudal & transverse cracks							
	noted in each span. Approximately 30% of the area has distress.							
	PX - Moderate to heavy scaling with delamination & spalls on the 2nd column near the ground on the West face (2009 photo). The 3rd column was patched (see #967) since 2007 -							
	the patch is separating. Minor spall at the upper west face of the 3rd column near the center.							
215	Some minor defects noted on the West near the center. Minor water stains are present on each abutment.							
224	The impall and Need 6 NE are 6th 2d are shown find a feb 2 d are 6 at the STE 6 are size and by Mark							
	There is a small spall on the North & NE area of the 3rd cap; on bottom of each end of the 2nd cap & at the top NE & two minor spalls on the bottom of the 1st cap at the North end. All are mainly due to insufficient cover. The SW corner of the 1st cap also has a small delamination. One moderate chip noted on the 1st cap near the west center area along							
	the top edge.							
310								
[								
331	FX - The SE corner post is loose at the curb level & the 1st rail section is a rough replacement. The 2nd post from the SE is cracked partially away from the curb & spalled at the							
	top. The NE curb is cracked badly below the corner post. Three other posts are spalled at the top. Lots of exposed rebar noted mainly due to insufficient cover. Some older patching							
	is evident - its deteriorating. There are a few other small defects in scattered areas.							
859	Less than 2% of the total area has any defects or distress.							
050								
958	8 FX - Light to moderate longitudal & transverse cracks noted in each span.							
962	DV. One minor this on the South adea of most #2 coffit trule surposed steel							
902	2 PX - One minor chip on the South edge of span #3 soffit w/o exposed steel.							
967	Minor paint marks on the 3rd cap with some paint marks noted in the soffit of span #4 (the 3rd column was patched since 2007 - its now coming loose). There are 4 moderate chips							
	in the SE edge of the 3rd column as well.							
Poads	way Name: I-35 UNDER  NBI Information Applicable To The Route Under The Structure							
	ventory Route (Route Under Structure: 2 - 1 - 1 - 00035 - 0   102. Traffic Dir.: 2 2-way traffic							
	fin. Vert. Clr.(ft.): 16.0   28b, Lanes Und.; 4   104. Highway System: 1 On the NHS							
	2007 2007							
	17000							
	Toll Facility: 3 On free road 51. Roadway Width (ft.): 74.5 114. Future ADT: 28160							
26. Fi	unction Class.: 01 Rural Interstate 100. Defense Highway: 1 On Interstate STRAHNET							
Age	ncy Field: 1.(Under Rte.): U 2.(Vert. X-Ref.): -1 3.(Compass Dir.): N 4.(Vert. Post. Inc.): 1600 5.(Vert. Post. Dec.): 1510							

1/4/2018 Page 2 of 2