OKLAHOMA DEPARTME	NT OF TRANSI	PORTAT	TION		Fridge Rating:	e Inspection	Report Health Index :
NBI No.: 15146 Structure No.: 3625	1299 X Local	ID:-1		2011	FO	/ = 1 =	85.3
Description: IDENTIFICATION					INSP	ECTION	
30'-55'-55'-30' CONT. CONC SLAB SPANS W/ 2-1.5' SA			nsp Req.	Insp Done	Freq:		<u>Next Insp.:</u>
1. State: Oklahoma 2. SHD District: I 3. County Code: KAY 4. Place Code: Unk		NBI:	N	Y	24	11/13/2017	11/13/2019
Admin. Area: Unknown	liowii	FC Freq.: UW Freq.:	N N	N N	NA NA	NA NA	NA NA
5. Inventory Route (Route On Structure) : 1 - 4 - 1 - E	0160 - 0	OS Freq.:	N	N	NA	NA	NA
6. Feature Intersected: I-35 UNDER					CLASSI	FICATION	
13. LRS Inv. Route./ Subroute.: -1 16. Latitude: 36 46 56.13 17. I	E0160 Mile Post: 12.987 mi congitude: 097 20 46.58 order Br. #: Unknown	21. Custodian 26. Functiona	: 01State Hi al Class: 07 Highway: 0	ighway Age Rural Mjr (Not a STR.	e Network ncy Collecto	20. Toll Facility: 3 On 22. Owner: 01 State H 37. Historical Sig.: 5 M 101. Parallel Structure: 103. Temp. Structure:	ighway Agency Not eligible for NRHP : No bridge exists
43. Main Span Material and Design Type Concrete Continuous Slab	ERIALS	104. Highway	System: 0	Not on NHS		105. Fed. Land Hwy (112. NBIS Length: Lo	N/A (NBI)
44. Approach Span Material and Design Type Not Applicable (P) Not Applicab	ale (D)				CON	DITION	
Not Applicable (P)Not Applicable45. No. of Spans Main Unit:446. No. of Approa		58. Deck: 6			9. Super.: 7		Sub.: 6 Satisfactory
107. Deck Type: 1 Concrete-Cast-in-Place		62. Culvert: Flowline No		BI) 6	1. Channel	Channel Protection: N	N/A (NBI)
108A. Wearing Surface: 0 None 108B. Membrane: 0 None		Flownile NO					
108B. Membrane: 0 None 108C. Deck Protection: None							
AGE AND SERVICE		<u> </u>		101		AND DOGTRIC	
	econstructed: -4	31. Design L	.oad: 2 M 13		D KAHN(<u>3 AND POSTING</u> 41. Posting status: A	Open, no restriction
28A. Lanes on: 2 28B. Lanes Under: 4	19. Detour Length: 2.0 mi			· · · ·	Factor-Ton	Alt. Op. Rating Meth.	•
29. ADT: 50 30. Year of ADT: 2015	109. Truck ADT %: 15	64. Operating	g Rating (H	/ HS / 3-3)	:	30.0 41.0	69.2
42A. Type of Service on: 1 Highway		66. Inventory				14.9 18.6	-1.1
42B. Type of Service under: 1 Highway			-			Alt. Inv. Rating Meth.	
GEOMETRIC DATA		70. Posting:	5 At/Above	-		Date Rated : 12/11/2	2007
10. Inv. Rte. Min. Vert. Clr.: 328.1 ft		04 D.11	Cost: 6-1		POSED IN	<u>APROVEMENTS</u>	21 Double - + C
32. Approach Roadway Width (W/ Shoulders): 20.5 ft		94. Bridge 0 95. Roadwa		88,846 136,596		75. Type of Work: 76. Lgth. of Improv	31 Repl-Load Capacit
Deck Area: 4,983.7 sq. ft 33. Median: 0 No median			•	,928,769		114. Future ADT: 8	
34. Skew: 0 35. Structure 47. Inv. Rte. Total Horiz. Clr.: 24.0 ft	Flared: 0 No flare	97. Year of	Cost Est.:	2015		115. Year of Future A	ADT: 2035
4/. Inv. Rte. Iotal Horiz. Cir.: 24.0 ft48. Length Maximum Span: 55.1 ft49. Structure	e Length: 171.9 ft					TION DATA	
	lewalk Width R: 1.5 ft	38. Naviga 39. Vertica			aterway	40. Horizontal Clea	rance: 0.0.ft
51. Width Curb to Curb: 24.0 ft 52. Width O	ut to Out: 29.0 ft	111. Pier Pr			le (P)	116. Lift Bridge Vert	
53. Minimum Vertical Clearance Over Bridge: 328.1 ft	ct 15.8 ft				APPI	RAISAL	
54A/54B. Min. Vert. Underclearance : H Hwy beneath stru <u>N/E</u> S/W	ct 15.8 ft	36A. Bridge	e Rail: 0 Sut	ostandard	-	36C. Approach Rail:	0 Substandard
<u>Meas.</u> N1511 N1602 -1 S1511	N1601 -1	36B. Transi				36D. Approach Rail En	
Post. DO NOT L DO NOT L DO NOT L DO N						 68. Deck Geometry: 2 Intolerable - Replace 	
55A/55B. Minimum Lateral Undrclearance R: H Hwy bene	ath struct 9.4 ft	71. Waterw				2 montane replace	
56. Minimum Lateral Undrclearance L: 19.0 ft		72. Approa	0			Crit	
		113. Scour (Critical: N	Not Over W	/aterway		
200c. Temperature: 52	214a. Posted Weight Limit:	NR NR				Girder Spacing/Numb	ber: -1.0 / -1
200d. Weather:CLOUDY201. Structural Steel ASTM Desig.:-1	 b. Posted Speed Limit : c. Narrow/One Lane Bridge 					Span Lengths : 30 30	-1
202. Waterproof Membrane :-1	d. Vertical Clearance Sign:	YES				55 -1	-1
Date Installed : 1/1/1901	Advanced Warning Sign	: NO				55 -1 Cinder Denth - 1.000	`
203. Type Exp. Dev. : _						. Girder Depth : -1.000 . Type of Overlay :	J
- 204 Type of Handrail: PC	e. Navigation Lights :	_				. Overlay Thickness :	0
204. Type of Handrail: BC 205. Material and Quantity : -1.0	Working/Not Working :	-					1/1/1901
208. Type of Abutment : Skeleton	215. Overpass : A - Interstate					6. Overlay Depth Chang 7. Protective Systems :	
Type of Foundation : Concrete Piling	221. Substructure Cond. (U/W) 222. Fill over RCB:	-1			24		3: _
209. Type of Pier / Found.: 1 Pier No Piling or Drilled Shaft	222. Fill over RCB: 223. Appr. Slab/Rdwy Cond.:	-1 Good			4:		5: _
210. Foundation Elev1.0-1.0		Not App	licable			No. of Field Splices v Scour Crit. POA exist	
-1.0 -1.0 -1.0	225. Paint Type : Overcoat :	Not App Not App				. Culvert Headwall Dis	
211. Wear. Surf. Prot. System : None	226. Date Painted:	-1			25	Char D Cl M C	Cture of D
Date Installed : 1/1/1901	227. Paint Coloring:	-1				 Chan. Profile Up/Dov a. OkiePROS Auto. Tru 	
213. Utilities Attached : -1 -1 -1 -1 -1	233. Deck Forming: Conventi	onai rorming				. Plans w/ found. are in	-
-1 -1 -1	238. School Bus Rte: Current a		ute		259	. Scour Eval. is in file a	at ODOT:
	240. Appr. Roadway Type: Gra	ivel				. Interchange at Interse . Interstate Milepoint:	ction: No Interchange 220.72
					204	. merstate whiepoint:	220.72

OKLAHOMA DEPARTMENT OF TRANSPORTATION -Bridge Inspection Report

Structure No.: 3625 1299 X NBI No.: 15146

-1

Local ID:-1

Suff. Rating: 72.1 FO

Health Index : 85.3

11/13/2017

GHINES Reported By:

Inspected With: Gary Richardson

Agency :

Structure / Inspection Notes

Maximum horizontal clearance below: N.B.= 43', S.B.=47' due to cable barriers & crash barrels.

G Hines inspection comments - 11/13/2017

Inspection Date:

Invoice No.:

PX - The upper area of the flume for the SE side drain is seriously undermined (2005 photo) - erosion is into the roadway edge \sim 2 ft * PX - All 4 side drains have shifted, settled & are broken up * PX - All slopewall sections are settled & separating & the cavities need filled SOON * Safety below = 1111 * PX - All of the OM-3's (above) are down - bent over on purpose by local farmers * Good gravel roadway

Elm.	Env.	Description	Un.	Qty.	Qty.St. 1	%1	Qty.St. 2	% 2	Qty.St. 3	%3	Qty.St. 4	%4	Qty.St. 5	% 5
38	4	Reinforced Concrete Slab	(SF)	4,126	1,651	40 %	2,475	60 %	0	0 %	0	0 %	0	0 %
205	4	Reinforced Conc Column or Pile Extension	(EA)	3	2	67 %	1	33 %	0	0 %	0	0 %	0	0 %
215	4	Reinforced Conc Abutment	(LF)	62	57	92 %	4	6 %	1	2 %	0	0 %	0	0 %
234	4	Reinforced Conc Cap	(LF)	81	64	79 %	5	6 %	12	15 %	0	0 %	0	0 %
331	4	Reinforced Conc Bridge Railing	(LF)	344	279	81 %	17	5 %	46	13 %	2	1 %	0	0 %
859	4	Soffit of Concrete Decks and Slabs	(EA)	1	0	0 %	1	100 %	0	0 %	0	0 %	0	0 %
958	4	Concrete Cracking	(EA)	1	0	0 %	0	0 %	1	100 %	0	0 %	0	0 %
962	4	Superstructure Traffic Impact	(EA)	1	0	0 %	1	100 %	0	0 %	0	0 %	0	0 %

Additional

Elements

Elem.		Element Notes (Include Size	e and Location of Dete	rioration						
	Some old deteriorated skim patches noted (10% of span #1). There is some light wear with exposed aggregate overall & minor grader damage. Some light to moderate pattern cracks of moderate density noted in wheel lanes - 60% of the deck has some type of minor distress.									
205	Moderate scale noted at the bottom of #2. Superficial defects otherwise.									
215	There are a few popout-type spalls present on the West abutment. One small spall on the upper West edge near the centerline. Water staining noted on each abutment.									
	PX - There are some small delaminations/spalls on th insufficient cover but still need covered or treated.	e bottom of each end of each cap. U	Up to a 6 ft area is affected	on the lower NE edge of the	2nd cap. Most spalls are due to					
331	PX - The SE corner of the curb is cracked badly from traffic impact (2009 photo). The 1st rail section is badly cracked near the SE post. Some minor spalling noted on a few posts. Lots of exposed rebar is visible on the rails in scattered areas due to insufficient cover. Still solid - minor weathering overall.									
	59 Some hairline cracking noted in each span w/o leaching or staining. There is a large crack at the SE corner of span #4 below the curb into the fascia (2009 photo) - caused by traffic impact to the rail. Not serious for now. Less than 2% of the total area has distress.									
958	8 PX - Some light to moderate pattern cracks of moderate density noted in wheel lanes.									
	962 Moderate chipping to the North edge of span #2 w/o exposed steel. Some minor scrapes noted under span #1. There is a large crack at the SE corner of span #4 below the curb into the fascia (2009 photo) - caused by traffic impact to the rail. None serious at this time.									
Roady	way Name : I-35 UNDER N	BI Information Applicable To T	he Route Under The Stru	icture						
5. Inv	ventory Route (Route Under Structure : 2 - 1 -	1 - 00035 - 0		102. Traffic Dir.:	2 2-way traffic					
10. M	in. Vert. Clr.(ft.): 15.8	28b. Lanes Und.:	4	104. Highway System :	1 On the NHS					
12. Ba	ase Hwy Network : On Base Network	29. ADT :	17600	105. Fed Land Hwy :	0 N/A (NBI)					
13. LI	RS Inv. Rt./ Subroute : 3625 W0000 / 02	32. Appr. Roadway Width (ft.) :	74.3	109. Truck ADT% :	36					
19. De	etour Len.(Mi.): 0.0	47. Total Horiz. Clr.(ft.):	47.0	110. Natl. Truck Network :	1 Part of natl network					
20. To	oll Facility : 3 On free road	51. Roadway Width (ft.) :	74.3	114. Future ADT :	28160					
26. Function Class.: 01 Rural Interstate 100. Defense Highway : 1 On Interstate STRAHNET										
Agei	ncy Field: 1.(Under Rte.): U 2.(Vert. X-	Ref.): -1 3.(Compa	uss Dir.): N 4.(Vert	Post. Inc.): 1509 5.	(Vert. Post. Dec.): 1509					