

**Attention: One or more violations have been cited on this report.
In addition, one or more Remedial Action reports are required.**

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Rhoads, Christopher		Inspector's Signature Christopher L. Rhoads		Digitally signed by Christopher L. Rhoads DN: cn=Christopher L. Rhoads, o=DOT/FRA, ou=DOT/FRA, email=christopher.rhoads@dot.gov, c=US Date: 2014.09.15 17:28:53 -0500		Inspector's ID No. 73163	Report No. 178	Date yy mm dd 2014 09 15					
Railroad/Company Name & Address BLACKWELL NORTHERN GATEWAY RAILROAD COMPANY 1910 West Ferguson Blackwell OK 74631				R/C R	Division SYSTEM	RR/Co. Representative (Receipt Acknowledged) Name Scott Nauer Title Director of Operations Email Signature _____							
From: City BLACKWELL	Codes 0420	Destination City & County				Codes	From Latitude						
State OK	40	City BLACKWELL				0420	From Longitude						
County KAY	C071	County KAY				C071	To Latitude						
Mile Post: From		To	Inspection Point SWITCH INSPECTION				To Longitude						
Activity Code:	TREC												
Units:	1												
Sub Units:	1												
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1		TREC		213	0241	F				N	N	1	TREC
Description FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-03N. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.													
Seal Applied		Seal Removed				Hazard Class			UN/NA ID				
Violation Recommended				<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input checked="" type="checkbox"/> Required	<input type="checkbox"/> Optional	Railroad Action Code		<input type="text"/>	Date(mm/dd/yyyy):		<input type="text"/>	Comments on back?	
Railroad Comments													

INSPECTION REPORT
(Continuation)

Inspector's ID No. 73163	Report No. 178	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-03S. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Railroad Comments

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-04N. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Railroad Comments

INSPECTION REPORT

(Continuation)

Inspector's ID No. 73163	Report No. 178	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-04S. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Railroad Comments

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-01N. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Railroad Comments

INSPECTION REPORT

(Continuation)

Inspector's ID No. 73163	Report No. 178	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-02N. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Railroad Comments

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
7		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-08N. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Railroad Comments

INSPECTION REPORT

(Continuation)

Inspector's ID No. 73163	Report No. 178	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
8		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-08S. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Railroad Comments

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
9		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-06N. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Railroad Comments

INSPECTION REPORT

(Continuation)

Inspector's ID No. 73163	Report No. 178	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
10		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-07N. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Railroad Comments

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
11		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-07S. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Railroad Comments

INSPECTION REPORT

(Continuation)

Inspector's ID No. 73163	Report No. 178	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
12		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-08XO. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Railroad Comments

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
13		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-06XO. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Railroad Comments

INSPECTION REPORT

(Continuation)

Inspector's ID No. 73163	Report No. 178	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
14		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-41N. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Railroad Comments

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
15		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-40. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Railroad Comments

INSPECTION REPORT

(Continuation)

Inspector's ID No. 73163	Report No. 178	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
16		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-50. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Railroad Comments

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
17		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-52. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Railroad Comments

INSPECTION REPORT

(Continuation)

Inspector's ID No. 73163	Report No. 178	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
18		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-53. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Railroad Comments

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
19		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-61. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Railroad Comments

INSPECTION REPORT

(Continuation)

Inspector's ID No. 73163	Report No. 178	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
20		SWITCH	T	213	0241	F				N	N	1	TREC

Description
FAILURE TO MAKE RECORDS AVAILABLE FOR COPYING AND INSPECTION. For the month of August 2014, Switch 400-62. Note: Each owner required to keep inspection records under this section shall make those records available for inspection and copying by the Federal Railroad Administration.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input checked="" type="checkbox"/> Required <input type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Railroad Comments

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
21										N	N	0	

Description - [Comment to Railroad/Company **]**
**A violation(s) is recommended with Civil Penalties for the defective conditions recorded on Line Item(s) No. 1. to Line Item(s) No.20 *

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Federal-aid Railroad Grade Crossing Project

STP-259D(014)RR, JP No. 30972(04)

The BNSF Railway Company and the Oklahoma Department of Transportation propose the installation of pedestal-mounted flashing light signals with gate arms, utilizing prediction circuitry at County Road N-3410 (DOT No. 673-715E), near Lela, Pawnee County, Oklahoma. It is agreed that this project will be financed with 90% Federal-aid Railroad Highway Grade Crossing Safety Funds - Section 130 Title funds and a matching 10% County funds for signal installation costs. The total estimated cost of this project is \$210,606.00. The estimated time for construction for this project is 12 months from the date of issuance of the Oklahoma Department of Transportation work order.

As directed by the Oklahoma Transportation Commission at its meeting of June 2, 2014, the Department is authorized to utilize State apportioned Federal-aid funds with matching State funds to construct said project. All work and the financing thereof shall be subject to the terms and provisions of the Master Agreement between the Department and The Burlington Northern Railroad dated October, 1993, and the attached Exhibit, supplement to the Master Agreements, and is in compliance with the laws of the State of Oklahoma.

BUY AMERICA: As required by Title 23 Code of Federal Regulations 635.410 and the ODOT Standard and Specifications Section 106.01.B, all manufacturing processes of steel or iron provided under this agreement shall occur in the United States, unless the cost of such materials used does not exceed one-tenth of one percent of the total contract cost or \$2,500, whichever is greater. Railroad agrees to state such compliance.

OKLAHOMA DEPARTMENT OF TRANSPORTATION

BNSF RAILWAY COMPANY

Deputy Director

Date

Director of Capital Programs

Date

General Counsel

Date

Division Manager

Date

Name

Title

Date





09/15/2014 11:52



09/15/2014 11:53



09/15/2014 11:53

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Rhoads, Christopher		Inspector's Signature				Inspector's ID No. 73163	Report No. 180	Date yy mm dd 2014 09 15					
Railroad/Company Name & Address BLACKWELL NORTHERN GATEWAY RAILROAD COMPANY 1910 West Ferguson Blackwell OK 74631					R/C R	Division SYSTEM	RR/Co. Representative (Receipt Acknowledged) Name Scott Nauer Title Director of Operations Email Signature						
From: City BLACKWELL		Codes 0420	Destination City & County			Codes	From Latitude 36.802483						
State OK		40	City OK/KS STATE LINE			9920	From Longitude -97.288086						
County KAY		C071	County KAY			C071	To Latitude 36.998768						
Mile Post: From 0035.60 To 18.30			Inspection Point SMT INSPECTION			To Longitude -97.410248							
Activity Code:	MTH	MTW	TOM	RWP	RMM	YTW							
Units:	17	3	4	1	2	1							
Sub Units:	0	0	0	1	0	0							
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	0034.50	YARD	Y	213	0109	C1	10	X		N	N	1	YTW
Description CROSSTIES, OTHER THAN CONCRETE, THAT MEET THE MINIMUM REQUIREMENTS OF PART 213.109 (B)(4), ARE BROKEN THROUGH. Multiple locations in the South Mill Track with X-Level measurement of 2 1/2 inches.													
Seal Applied		Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude: 36.802517			Longitude: -97.287979						
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?					
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	0034.50	YARD	T	213	0037	C3	10	X		N	N	1	TOM
Description EXCESSIVE VEGETATION IN TOEPATHS AND AROUND SWITCHES WHERE EMPLOYEES ARE PERFORMING NORMAL TRACKSIDE DUTIES. Multiple locations within the Yard of Blackwell Ok.													
Seal Applied		Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude: 36.802448			Longitude: -97.288147						
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?					

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	0018.40	MAIN	M	213	0037	E3	10	X		N	N	1	MTW

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS. MP 18.40 extending south.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.997684	Longitude: -97.410301
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	0019.10	BRIDGE	M	213	0033	A2	10	X		N	N	1	MTW

Description
DRAINAGE OR WATER-CARRYING FACILITY OBSTRUCTED BY DEBRIS. Bridge both sides.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.987751	Longitude: -97.409149
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	0019.50	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.982967	Longitude: -97.403801
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6	0019.50	BRIDGE	M	213	0033	A2	10	X		N	N	1	MTH

Description
DRAINAGE OR WATER-CARRYING FACILITY OBSTRUCTED BY DEBRIS.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.9818	Longitude: -97.402481
-----------------------	---	-------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

INSPECTION REPORT

(Continuation)

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
7	0019.50	MAIN	M	213	0109	B4	10	X		N	N	1	MTW

Description
FAILURE TO MAINTAIN THE MINIMUM NUMBER OF CROSSTIES PER FRA TRACK CLASS FOR EACH 39-FOOT SEGMENT OF TRACK AS INDICATED IN TABLE IN THIS SECTION. 3 NON-DEFECTIVE TIES PER 39' SEGMENT OF TRACK WITH 2 3/4" OF X-LEVEL.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.980316	Longitude: -97.400787	
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
8	0019.70	MAIN	M	213	0109	B4	10	X		N	N	1	MTW

Description
FAILURE TO MAINTAIN THE MINIMUM NUMBER OF CROSSTIES PER FRA TRACK CLASS FOR EACH 39-FOOT SEGMENT OF TRACK AS INDICATED IN TABLE IN THIS SECTION. 3 NON-DEFECTIVE TIES PER 39' SEGMENT OF TRACK WITH 4 1/2" OF X-LEVEL.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.980301	Longitude: -97.400818	
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
9	0019.70	MAIN	M	213	0103	D	10	X		N	N	1	MTW

Description
INSUFFICIENT BALLAST FAILING TO MAINTAIN PROPER GEOMETRY. 4 1/2" X -Level

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.980301	Longitude: -97.400818	
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
10	0019.80	MAIN	M	213	0037	B2	10	X		N	N	1	MTH

Description
VEGETATION OBSTRUCTS VISIBILITY OF GRADE CROSSING WARNING SIGNS AND SIGNALS BY THE TRAVELING PUBLIC.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.978569	Longitude: -97.398811	
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?

INSPECTION REPORT
(Continuation)

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
11	0020.00	MAIN	M	213	0037	B1	10	X		N	N	1	MTW

Description
VEGETATION OBSTRUCTS VISIBILITY OF RAILROAD SIGNS AND FIXED SIGNALS.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.978001	Longitude: -97.398148
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
12	0020.00	MAIN	M	213	0037	E3	10	X		N	N	1	MTW

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS Between MP 20.05 & MP 20.2...

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.975784	Longitude: -97.39563
-----------------------	---	---------------------	----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
13	0020.20	MAIN	M	213	0063	A5	10	X		N	N	1	MTW

Description
DIFFERENCE IN CROSSLEVEL (WARP) BETWEEN ANY TWO POINTS LESS THAN 62-FEET APART ON TANGENT TRACK EXCEEDS ALLOWABLE. A measurement of 3 1/8" inches.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.973866	Longitude: -97.393448
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
14	0020.40	MAIN	M	213	0037	A	10	X		N	N	1	MTH

Description
COMBUSTIBLE VEGETATION AROUND TRACK-CARRYING STRUCTURES. Bridge.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.973034	Longitude: -97.392517
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

INSPECTION REPORT
(Continuation)

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
15	0020.40	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.972584	Longitude: -97.391998
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
16	0020.50	MAIN	M	213	0037	A	10	X		N	N	1	MTH

Description
COMBUSTIBLE VEGETATION AROUND TRACK-CARRYING STRUCTURES. Bridge.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.971802	Longitude: -97.391113
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
17	0020.70	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.969749	Longitude: -97.388779
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

INSPECTION REPORT
(Continuation)

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
18	0020.85	MAIN	M	213	0109	B4	10	X		N	N	1	MTW

Description
FAILURE TO MAINTAIN THE MINIMUM NUMBER OF CROSSTIES PER FRA TRACK CLASS FOR EACH 39-FOOT SEGMENT OF TRACK AS INDICATED IN TABLE IN THIS SECTION. 2 NON- DEFECTIVE TIES PER 39' SEGMENT OF TRACK WITH 2 3/4" X-LEVEL.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.968002	Longitude: -97.386818
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
19	0021.35	MAIN	M	213	0063	A5	10	X		N	N	1	MTW

Description
DIFFERENCE IN CROSSLEVEL (WARP) BETWEEN ANY TWO POINTS LESS THAN 62-FEET APART ON TANGENT TRACK EXCEEDS ALLOWABLE. A measurement of 3 1/4" Warp.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.963833	Longitude: -97.38205
-----------------------	---	---------------------	----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
20	0021.35	MAIN	M	213	0109	B3	10	X		N	N	1	MTW

Description
NO EFFECTIVE SUPPORT TIES WITHIN THE PRESCRIBED DISTANCE FROM A JOINT. Multiple location between MP 21.3 to 21.5 were there is no effective joint tie at the joints.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.963734	Longitude: -97.38195
-----------------------	---	---------------------	----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

INSPECTION REPORT
(Continuation)

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
21	0021.55	MAIN	M	213	0063	A5	10	X		N	N	1	MTW

Description
DIFFERENCE IN CROSSLEVEL (WARP) BETWEEN ANY TWO POINTS LESS THAN 62-FEET APART ON TANGENT TRACK EXCEEDS ALLOWABLE. A measurement of 3 1/8"

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.960018	Longitude: -97.377739
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
22	0021.65	MAIN	M	213	0063	A3	10	X		N	N	1	MTW

Description
DEVIATION FROM ZERO CROSSLEVEL AT ANY POINT ON TANGENT EXCEEDS ALLOWABLE. A measurement of 3 1/8 X-Level.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.957901	Longitude: -97.375336
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
23	0021.65	MAIN	M	213	0033	A1	10	X		N	N	1	MTW

Description
DRAINAGE OR WATER-CARRYING FACILITY NOT MAINTAINED. Bridge.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.957901	Longitude: -97.375336
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
24	0021.95	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 0	Longitude: 0
-----------------------	---	-------------	--------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

INSPECTION REPORT
(Continuation)

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
25	0022.10	MAIN	M	213	0037	B1	10	X		N	N	1	MTW

Description
VEGETATION OBSTRUCTS VISIBILITY OF RAILROAD SIGNS AND FIXED SIGNALS. Home Road Crossing.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.956249	Longitude: -97.373451
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
26	0022.10	MAIN	M	213	0033	A1	10	X		N	N	1	MTW

Description
DRAINAGE OR WATER-CARRYING FACILITY NOT MAINTAINED. Bridge .

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.955067	Longitude: -97.37207
-----------------------	---	---------------------	----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
27	0022.20	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.953316	Longitude: -97.370132
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
28	0022.50	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS Between MP 22.5 to MP 22.8.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.950352	Longitude: -97.366783
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
29	0022.70	MAIN	M	213	0113	D12	10	X		N	N	1	MTW

Description
ORDINARY BREAK, 100% break out in rail head at joint, 3rd joint south of approach on bridge.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.948383	Longitude: -97.364632
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
30	0022.70	MAIN	M	213	0033	A1	10	X		N	N	1	MTW

Description
DRAINAGE OR WATER-CARRYING FACILITY NOT MAINTAINED. East side of bridge.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.948402	Longitude: -97.364548
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
31	0022.70	MAIN	M	213	0113	D16	10	X		N	N	1	MTW

Description
VERTICAL SPLIT HEAD, 3rd rail from south of approach on bridge.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.948418	Longitude: -97.364548
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
32	0022.70	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.947666	Longitude: -97.363686
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

INSPECTION REPORT

(Continuation)

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
33	0022.90	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.94635	Longitude: -97.362198
---	--------------------	-----------------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
34	0023.10	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.942902	Longitude: -97.358231
---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
35	0023.30	MAIN	M	213	0109	B3	10	X		N	N	1	MTW

Description
NO EFFECTIVE SUPPORT TIES WITHIN THE PRESCRIBED DISTANCE FROM A JOINT. Multiple locations between MP 23.25 to MP 23.3.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.941151	Longitude: -97.356316
---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
36	0023.60	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.938499	Longitude: -97.353264
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
37	0023.80			213	0037	E3	10	X		N	N	1	MTW

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS MP 23.8 to MP 24.7

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.936199	Longitude: -97.350647
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
38	0024.30	MAIN	M	213	0109	B4	10	X		N	N	1	MTW

Description
FAILURE TO MAINTAIN THE MINIMUM NUMBER OF CROSS-TIES PER FRA TRACK CLASS FOR EACH 39-FOOT SEGMENT OF TRACK AS INDICATED IN TABLE IN THIS SECTION. 3 NON-Defective ties per 39' segment of track.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.934002	Longitude: -97.348167
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

INSPECTION REPORT

(Continuation)

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
39	0024.30	MAIN	M	213	0033	A1	10	X		N	N	1	MTW

Description
DRAINAGE OR WATER-CARRYING FACILITY NOT MAINTAINED. Bridge.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.93187	Longitude: -97.345787
---	--------------------	-----------------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
40	0024.50	MAIN	M	213	0109	B4	10	X		N	N	1	MTW

Description
FAILURE TO MAINTAIN THE MINIMUM NUMBER OF CROSSTIES PER FRA TRACK CLASS FOR EACH 39-FOOT SEGMENT OF TRACK AS INDICATED IN TABLE IN THIS SECTION. 3 NON-Defective ties per 39' segment.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.930286	Longitude: -97.343987
---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
41	0024.75	MAIN	M	213	0127	A2	10	X		N	N	1	MTW

Description
INSUFFICIENT FASTENERS IN A TRACK SEGMENT. 2 inch vertical movement in old crossing.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
42	0024.95	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.924736	Longitude: -97.337685
---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

INSPECTION REPORT

(Continuation)

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
43	0025.05	SWITCH	M	213	0037	C3	10	X		N	N	1	TOM

Description
EXCESSIVE VEGETATION IN TOEPATHS AND AROUND SWITCHES WHERE EMPLOYEES ARE PERFORMING NORMAL TRACKSIDE DUTIES.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended Yes No Latitude: 36.92395 Longitude: -97.336784

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
44	0025.07	SWITCH	M	213	0037	C3	10	X		N	N	1	MTH

Description
EXCESSIVE VEGETATION IN TOEPATHS AND AROUND SWITCHES WHERE EMPLOYEES ARE PERFORMING NORMAL TRACKSIDE DUTIES.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended Yes No Latitude: 36.922916 Longitude: -97.335655

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
45	0025.37	MAIN	M	213	0037	E3	10	X		N	N	1	MTW

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended Yes No Latitude: 36.920517 Longitude: -97.332916

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
46	0025.45	MAIN	M	213	0037	C3	10	X		N	N	1	TOM

Description
EXCESSIVE VEGETATION IN TOEPATHS AND AROUND SWITCHES WHERE EMPLOYEES ARE PERFORMING NORMAL TRACKSIDE DUTIES.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended Yes No Latitude: 36.91927 Longitude: -97.331482

Written Notification to FRA of Remedial Action is: Required Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
47	0025.50	MAIN	M	213	0063	A5	10	X		N	N	1	MTW

Description
DIFFERENCE IN CROSSLEVEL (WARP) BETWEEN ANY TWO POINTS LESS THAN 62-FEET APART ON TANGENT TRACK EXCEEDS ALLOWABLE. A measurement of 3 1/8" inches.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.917118	Longitude: -97.329018
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
48	0025.60	MAIN	M	213	0033	A1	10	X		N	N	1	MTW

Description
DRAINAGE OR WATER-CARRYING FACILITY NOT MAINTAINED. Bridge

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.91655	Longitude: -97.328415
-----------------------	---	--------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
49	0025.70	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS MP 25.75 to 26.25

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.914867	Longitude: -97.326485
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
50	0026.30	MAIN	M	213	0033	A1	10	X		N	N	1	MTH

Description
DRAINAGE OR WATER-CARRYING FACILITY NOT MAINTAINED.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.90992	Longitude: -97.320869
-----------------------	---	--------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

INSPECTION REPORT

(Continuation)

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
51	0026.30	MAIN	M	213	0127	A2	10	X		N	N	1	MTH

Description
INSUFFICIENT FASTENERS IN A TRACK SEGMENT. 2.5 inches.south approach of bridge.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.908752	Longitude: -97.319496
---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
52	0026.60	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.906536	Longitude: -97.31723
---	---------------------	----------------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
53	0026.78	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.903851	Longitude: -97.31469
---	---------------------	----------------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
54	0027.10	MAIN	M	213	0033	A4	10	X		N	N	1	MTH

Description
DRAINAGE OR WATER-CARRYING FACILITY OBSTRUCTED BY VEGETATION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.900551	Longitude: -97.3116
---	---------------------	---------------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
55	0027.20	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.898518	Longitude: -97.309685
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
56	0027.35	MAIN	M	213	0037	B2	10	X		N	N	1	MTH

Description
VEGETATION OBSTRUCTS VISIBILITY OF GRADE CROSSING WARNING SIGNS AND SIGNALS BY THE TRAVELING PUBLIC. Earth road.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.897533	Longitude: -97.308769
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
57	0027.55	MAIN	M	213	0037	B1	10	X		N	N	1	MTH

Description
VEGETATION OBSTRUCTS VISIBILITY OF RAILROAD SIGNS AND FIXED SIGNALS. Whistle post.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.895103	Longitude: -97.306435
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
58	0027.75	MAIN	M	213	0033	A4	10	X		N	N	1	MTH

Description
DRAINAGE OR WATER-CARRYING FACILITY OBSTRUCTED BY VEGETATION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.892735	Longitude: -97.304207
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
59	0028.15	MAIN	M	213	0033	A4	10	X		N	N	1	MTH

Description
DRAINAGE OR WATER-CARRYING FACILITY OBSTRUCTED BY VEGETATION.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.889351	Longitude: -97.301056
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
60	0028.20	MAIN	M	213	0037	B2	10	X		N	N	1	MTH

Description
VEGETATION OBSTRUCTS VISIBILITY OF GRADE CROSSING WARNING SIGNS AND SIGNALS BY THE TRAVELING PUBLIC.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.888367	Longitude: -97.300056
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
61	0028.35	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.88702	Longitude: -97.298813
-----------------------	---	--------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
62	0028.45	MAIN	M	213	0037	B2	10	X		N	N	1	MTH

Description
VEGETATION OBSTRUCTS VISIBILITY OF GRADE CROSSING WARNING SIGNS AND SIGNALS BY THE TRAVELING PUBLIC.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.882965	Longitude: -97.294998
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

INSPECTION REPORT

(Continuation)

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
63	0028.65	SWITCH	T	213	0135	D	10	X		N	N	1	TOM

Description
HEEL OF SWITCH INSECURE.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.880833	Longitude: -97.293068
---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
64	0029.15	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.876949	Longitude: -97.291565
---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
65	0029.35	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.872799	Longitude: -97.291603
---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
66	0030.60	MAIN	M	213	0037	B2	10	X		N	N	1	MTH

Description
VEGETATION OBSTRUCTS VISIBILITY OF GRADE CROSSING WARNING SIGNS AND SIGNALS BY THE TRAVELING PUBLIC.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.855133	Longitude: -97.291519
---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
67	0030.65	MAIN	M	213	0033	A2	10	X		N	N	1	MTH

Description
DRAINAGE OR WATER-CARRYING FACILITY OBSTRUCTED BY DEBRIS.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.853367	Longitude: -97.291481
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
68	0031.60	MAIN	M	213	0037	B2	10	X		N	N	1	MTH

Description
VEGETATION OBSTRUCTS VISIBILITY OF GRADE CROSSING WARNING SIGNS AND SIGNALS BY THE TRAVELING PUBLIC. Break road.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.840248	Longitude: -97.290932
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
69	0031.80	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.836567	Longitude: -97.290199
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
70	0032.35	MAIN	M	213	0063	A3	10	X		N	N	1	MTW

Description
DEVIATION FROM ZERO CROSSLEVEL AT ANY POINT ON TANGENT TRACK EXCEEDS ALLOWABLE A measurement of 3 1/4 X-Level.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
71	0032.75	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude: 36.825115	Longitude: -97.289886
-----------------------	------------------------------	--	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	-----------------------------------	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
72	0033.75	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS Mp to 34.5

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude: 36.810066	Longitude: -97.287766
-----------------------	------------------------------	--	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	-----------------------------------	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
73	0034.25	MAIN	M	213	0037	C3	10	X		N	N	1	MTH

Description
EXCESSIVE VEGETATION IN TOEPATHS AND AROUND SWITCHES WHERE EMPLOYEES ARE PERFORMING NORMAL TRACKSIDE DUTIES. Switchs north end of town.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude: 36.802349	Longitude: -97.28775
-----------------------	------------------------------	--	---------------------	----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	-----------------------------------	--	----------------------	-------------------	-------------------

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
74	0034.65	MAIN	M	213	0037	B2	10	X		N	N	1	MTH

Description
VEGETATION OBSTRUCTS VISIBILITY OF GRADE CROSSING WARNING SIGNS AND SIGNALS BY THE TRAVELING PUBLIC. 6th street crossing.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.798698	Longitude: -97.292267
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
75	0034.75	MAIN	M	213	0037	E3	10	X		N	N	1	MTH

Description
VEGETATION BRUSHING SIDES OF ROLLING STOCK THAT PREVENTS EMPLOYEES FROM VISUALLY INSPECTING MOVING EQUIPMENT FROM THEIR NORMAL DUTY STATIONS

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.798748	Longitude: -97.294853
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
76	0126.45	MAIN	M	213	0115	A3	10	X		N	N	1	MTW

Description
RAIL-END MISMATCH ON GAGE SIDE OF RAIL EXCEEDS ALLOWABLE. A mesurement of 3/8 inches at 2nd joint north of crossing, on west rail.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.800148	Longitude: -97.300888
-----------------------	---	---------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 73163	Report No. 180	Report Date 9/15/2014
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
77	0125.55	MAIN	M	213	0109	C2	10	X		N	N	1	MTW

Description
CROSSTIES, OTHER THAN CONCRETE, THAT MEET THE MINIMUM REQUIREMENTS OF PART 213.109 (B)(4), ARE SPLIT OR OTHERWISE IMPAIRED TO THE EXTENT THE CROSSTIE WILL ALLOW THE BALLAST TO WORK THROUGH, OR IT WILL NOT HOLD SPIKES OR RAIL FASTENERS. With a profile measurement of 2 1/2"....

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude: 36.80415	Longitude: -97.316963
-----------------------	---	--------------------	-----------------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------